V8 VANTAGE LH MIRROR BRACKET

AWV8VLH







£180.00

£216.00 inc VAT

Product Description:

A common issue on VH-era V8 and V12 Vantages is corrosion of the wing mirror stalk, caused by a breakdown in the powder coating.
These are only available from Aston Martin as a full mirror assembly. These brackets are now available on an exchange basis from Aston Workshop at a fraction of the cost of a complete mirror assembly. Coated in a 2-stage primer and powder coat they are finished as per the originals but won't succumb to the same corrosion issues.
These stalks fit the following Aston Martin part numbers:
6G33-17682-AG, 7G33-17682-AB, 6G33-17682-BG, 7G33-17682-BB, AG33-17682-AF, GD2Y-17682-AB, AG33-17682-BD, 6G33-17683-AG, 7G33-17683-AB, 6G33-17683-BG, 7G33-17683-BB, AG33-17683-AF, GD2Y-17683-AB, AG33-17683-BD.
To order, please call our parts department on +44 (0) 1207 233525
We also offer a supply and fit service at a cost of 550 plus vat per pair. To make an appointment please call our Service Manager Chris on +44 (0) 1207 233525
PLEASE NOTE AN ADDITONAL SURCHARGE PAYMENT OF Â£125 IS REQUIRED PER UNIT, WHICH IS REFUNDABLE UPON RETURN OF THE ORIGINAL BRACKET.

Further Images:

