

## V8 VANTAGE RH MIRROR BRACKET

AWV8VRH



**£180.00**  
**£216.00 inc VAT**

### Product Description:

A common issue on VH-era V8 and V12 Vantages is corrosion of the wing mirror stalk, caused by a breakdown in the powder coating.

These are only available from Aston Martin as a full mirror assembly. These brackets are now available on an exchange basis from Aston Workshop at a fraction of the cost of a complete mirror assembly. Coated in a 2-stage primer and powder coat they are finished as per the originals but won't succumb to the same corrosion issues.

These stalks fit the following Aston Martin part numbers:

6G33-17682-AG, 7G33-17682-AB, 6G33-17682-BG, 7G33-17682-BB, AG33-17682-AF,  
GD2Y-17682-AB, AG33-17682-BD, 6G33-17683-AG, 7G33-17683-AB, 6G33-17683-BG,  
7G33-17683-BB, AG33-17683-AF, GD2Y-17683-AB, AG33-17683-BD.

To order, please call our parts department on +44 (0) 1207 233525

We also offer a supply and fit service at a cost of 550 plus vat per pair. To make an appointment please call our Service Manager Chris on +44 (0) 1207 233525

PLEASE NOTE AN ADDITIONAL SURCHARGE PAYMENT OF Â£125 IS REQUIRED PER UNIT, WHICH IS REFUNDABLE UPON RETURN OF THE ORIGINAL BRACKET.

### Further Images:

